

Original post set 1820 by Hendricks with witness: 20" hickory N 3 W 22 links, 13" elm S 30 W 3 links per Marion County Atlas p.g. 9. Fatout 11-10-1849 called no stone; but witness: (2) 50" oaks N 83 E 50 links per Franklin Township Legal Survey Book pg. 26. GWS 10-1-63 didn't call type of marker. Wilcoxen 7-23-75 called PK nail. Wilcoxen 4-27-90 called same. Excavated by Wilcoxen 4-24-95 and PK nail found at surface. Railroad spike found 3" down under PK nial. No stone found due to pipe running through the corner. Harrison set. Re-tied 4-19-98 by Wilcoxen. Re-tied 9-25-04 by Wilcoxen.

REF.	DISTANCE	DESCRIPTION
1.	71.15	Cut 'x' SW-bolt signal base
2.	83.90'	Cut 'x' NW-bolt signal base
3.	69.43'	Cut 'x' NE-bolt signal base
4.	66.36	Top nut of fire hydrant
5.	82.72	SW corner of metal signal box
6.	77.54	Cut 'x' SE-bolt signal base
,		
	L.	·